

Department of Homeland Security 10 Print Scanner Impacts

Neal Latta
Dave Williams
October 14, 2005



DHS Border Management Operations requiring 10-print capability

- Primary Inspections Screening (US-VISIT)
 - 2500 scanner units
 - 30 million travelers processed each year
- Secondary Inspections Processing
 - 600 scanner units
 - Over 250K subjects processed each year
- Border Patrol Operations
 - 400 scanner units
 - Over 1.2M subjects processed each year
- ICE Enforcement Operations
 - 250 scanner units
 - Over 300 K subjects processed each year
- Benefits Processing

2 million persons processed each year



US-VISIT Goals

- □ Enhance National Security
- □ Improve the Integrity of the Immigration Process
- □ Facilitate legitimate trade and travel
- □ Protect the privacy of our visitors



US-VISIT Current Implementation


- □ 115 Air and Sea Ports of Entry
- □ 165 Land Border Ports of Entry
- Challenges met during initial 2-print implementation at POEs
 - No additional personnel available
 - No major facility modifications possible
 - No increase in wait times permitted
- □ Results
 - No increases in wait times at air and sea POEs
 - Decrease in wait times at land POEs
 - US-VISIT operations merged smoothly into inspections process

90 thousand persons processed every day




The Challenge

- □ Speed
 Current capture time is measured at 12 seconds
- □ Quality
 Best possible quality, at least as high as today's single-print devices
- □ Size
 Small enough to fit on a typical POE lane counter top
- □ Usability
 - Light weight
 - Single data/power cable no extra power outlet






Scanner Size Impact – height concerns



Note the Fingerprint Scanner in a drawer



Scanner Size Impact – depth concerns



Counter/fingerprint scanner (Traveler View)



Scanner Size Impact – Workspace Limited



Figure 1: Travelers View – Workstation (Typical)



Scanner Cabling Impact



Figure 2: Inspections View – Workstation – Handicap accessible counter made available



Scanner Operating Environment



Figure 1: Inspections View – Workstation (Typical)

NOTE: Tray to pass fingerprint scanner and glass